



Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

July 15, 1991

TO: Minerals File

FROM: Holland Shepherd, Senior Reclamation Specialist *HS*

RE: Site Inspection, Kell's Mine, Brian Light, S/049/017, Utah County, Utah

Date of Inspection: July 10, 1991
Time of Inspection: 11:00 a.m. - 12:00 a.m.
Conditions: Sunny, hot, clear, dry
Participants: Holland Shepherd, DOGM

I stopped at the Kell's mine site today, which is located just about 1 mile northwest of the Tucker Rest Area, off of Highway 6, Spanish Fork Canyon. Mr. Brian Light, operator of the mine site, had informed me earlier last month that the cabin, outhouse, and other living facilities that had been established at the mine site in the summer of 1990 would be removed in the late spring of 1991. Everything has been removed from the site as promised by Mr. Light. All that remains is an access road into the site. The road is not badly disturbed and will eventually revegetate itself. Presently there are grasses and forbs growing on the road.

Mr. Light had been asked to remove the facilities because of their proximity to Starvation Creek and the potential impact to the natural, perennial stream channel.

Mr. Light indicated that he was talking to another individual who was interested in taking over the responsibilities of operating the site, but nothing was definite as of yet. No activities are evident at the site at this date.

jb
cc: Brain Light, Operator
Wayne Hedberg
S049017.1